



Uzemňovacie príchytky PLNS

PLNS - 00 N




2PLNS - 1,2 N




	2PLNS - 1N	2PLNS - 2N
B	175,6	200
C	200	230
D	25	30


OS 00, OS 12




P00, P1, P2, P3



P002, P12, P22, P32



«V» úchyty



Technické údaje

typ	a	b	c	d	e _{max}
OS00	24	15	15	M5	15
OS12	36	16	25	M6	25
P00	24	15	15	M5	25
P002	24	15	15	M5	35
P1	37	20	25	M6	30
P12	37	20	25	M6	42
P2	42	22	28	M8	40
P22	42	22	28	M8	55
P3	50	25	30	M8	44
P32	50	25	30	M8	66